

MIRAWIPE®: REFLECTOR PLATE (RTA) PARTICLE DATA

- Below is the Defect On Wafer (DOW) Instability Chart
- MiraWIPES® were implemented on WW34
- “MiraWIPES® have cut WAY down on damage done to REFLECTOR PLATE” (RTA Engineer)
- “MiraWIPES® have a very porous surface and do an amazing job at “lifting” the particles from surfaces vs. pushing particles around like our other fab wipers” (RTA Engineer)

